



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB381

**Issue Date:** 5-10-2016

**Available:** 5-17-2016




**Product Description:**

Change to N51-01, N51-05, N51-06

**Part No:**

N51-01, N51-05, N51-06

**Specification:**



**Comments:**

The N51-01, N51-05 and N51-06 nozzles have changed with an upgraded pipe guard that will prevent the use of the vacuum pickup and will prevent damage to the unit. The new nozzles will be denoted on the outside of the nozzle by a "G" following the part number.

**Note: If using an older N51-01, N51-05 or N51-06 without a "G" denoted on the outside of the nozzle, do not use the vacuum pickup feature as you can cause damage to your unit. Please refer to PB378 FR-810B Hot Air Rework Station and the FR-810B User Manual, Section 4 for more information.**

For more information please visit us at [www.HakkoUSA.com](http://www.HakkoUSA.com). For information regarding nozzle compatibility, please visit our knowledgebase at [KB.HakkoUSA.com](http://KB.HakkoUSA.com).

AHP14 Rev 2012-11

28920 Avenue Williams · Valencia · California 91355

Tel 661.294.0090 · Fax 661.294.0096 · [www.HakkoUSA.com](http://www.HakkoUSA.com)