Sentry

USES:

- Production Testing of Appliances, Instruments and Information Technology Equipment in Accordance with UL,IEC,TÜV and Other Standards such as EN60335, EN60950, EN61010, CSA C22.2 No. 1010.1, UL3111 and UL1950
- Transformer Electrical Safety Testing
- Electric Motor Safety Testing
- Variety of Electronic Components
- Testing Electronic Components

FEATURES:

- Easy to Use
- Cost Effective Solution for Hipot and IR
- Programmable Output Voltage to 5KV AC and 6KV DC
- Programmable Ramp and Test Times
- Programmable High and Low Limits
- Quick Discharge of DUT in IR and DC Hipot
- Storage of 40 2-Step Tests or 80 1-Step Tests
- Remote Control
- Ground Continuity Check with John Limit
- Front Panel Lockout
- Arc Detection with Programmable Limit
- Resistance Measurements from $10M\Omega$ to $10G\Omega$
- CE Mark Models (Sentry 15, 25, 35)

Series Hipot Testers

Economical AC/DC/IR Hipot Testers

Introduction

A complete dielectric testing solution, with three models from which to choose. The Sentry 10 for AC Hipot testing, the Sentry 20 for AC/DC Hipot testing, and the Sentry 30 which combines both AC and DC Hipot with insulation resistance (IR) measurements into a single compact unit. The front panel of the Sentry makes it easy to operate. Digital display and user friendly control allows test parameters and limits to be set easily without the high voltage activated.

These three units are also available in a CE Mark version, the Sentry 15 for AC Hipot, Sentry 25 for AC/DC Hipot and the Sentry 35 for AC/DC Hipot and IR.

Description

The Sentry Series of electrical safety testers are advanced digital hipots with load and line regulation to ensure measurement integrity. Multistep capability allows the user to perform up to two tests in a sequence such as AC hipot followed by IR.

The Sentry 10/15 AC Hipot Tester performs AC dielectric withstand (hipot) tests. The test voltage can be programmed in the range from 100V AC to 5kV AC with a resolution of 10V. The maximum total output current is 15mA.

The Sentry 20/25 AC/DC Hipot Tester has all the features of the Sentry 10/15 with the addition of DC hipot capability. The test voltage can be programmed in the range from 100V DC to 6kV DC with a resolution of 10V. The maximum total current is 7.5mA (5.0mA for the CE Mark version, Sentry 25).

The Sentry 30/35 AC/DC/IR Hipot Tester has all of the features of the Sentry 10/15 and 20/25 plus measurement of insulation resistance. The IR measurement range is from $10M\Omega$ to $10G\Omega$ with test voltages from 50 to 1000V DC.

Quick Discharge: In both the DC hipot and IR the device under test is discharged back through the HV transformer. This technique results in a rapid and safe discharge.

Ground Continuity Check: All of the Sentry units have a ground continuity check feature to determine that the resistance, between the ground blade of the power cord and any exposed metal on the product, is less than 1 ohm.



For more detailed specifications, visit www.quadtech.com

For more information about special purchase, rent & lease options, call

1-800-253-1230 Fax 1-978-461-4295 Intl. 1-978-461-2100





Sentry 10, 20, 30, and 15, 25, 35

AC Output Voltage: Range: 100V to 5000V AC

Resolution: 10Volts/step Frequency: 50/60 Hz selectable Frequency Accuracy: 100ppm

Waveform: Sinusoidal

Regulation: +/-(1% of setting +5V)

Voltage Display: Accuracy: +/-(1% of reading + 5V)

Resolution: 1Volt

AC Current Display: Total current

Range: 0.001 to 15mA AC

Resolution: 1µA

Accuracy:+/-(1.5% of reading + 5cnt)

High/Low Limit Test: 1μA to 15mA AC

Accuracy: +/-(1% of limit + 5cnt)
Low limit can be turned OFF

Sentry 20, 30 and 25, 35

DC Output Voltage: Range: 100V to 6000V DC

Resolution: 10Volts/step

Regulation: $\pm (1\% \text{ of setting } \pm 5\text{V})$

Voltage Display: Accuracy: +/-(1% of reading + 5V)

Resolution: 1Volt

DC Current Display: Range: 1μA to 7.5mA DC

(5.0mA for Sentry 25, 35)

Resolution: $1\mu A$

Accuracy:+/-(1.5% of reading + 5cnt)

High/Low Limit Test: 1µA to 7.5mA DC

(5mA for Sentry 25, 35) Low limit can be turned OFF

Charging Current: 7.5mA max (5mA for Sentry 25, 35)

Sentry 30 and 35

Insulation Resistance: Range: $10M\Omega - 10G\Omega$

+/- (10% of reading + 10 cts), \geq 500V +/- (15% of reading + 10 cts), <500V Voltage Range: 50V to 1000V DC Accuracy: +/-(1% of setting +5V)

High/Low Limit Test: $10M\Omega - 10G\Omega$

High limit can be turned OFF

Charging Current: 7.5mA max (5mA for Sentry 35)

Common Features

Arc Detection: Arc Level: >1mA - 15mA or OFF

Arc Duration: > 10µs

Indication: Pass/fail lights, audible sound

Buzzer Level: On / Off

Time: Ramp: 0.1 to 999s (+/-20ms)

Test: 0.1 to 999s (+/-20ms) and

Continuous

Quick Discharge: Discharge of voltage across DUT back

through the HV transformer

Ground Continuity: High Limit: 1Ω

Accuracy: $\pm -0.1\Omega$

Test Current: 100 mA DC

Remote Control: Inputs: Start, Stop and Interlock

Characteristics: 24V Active Low,

Pulse Width >1ms.

Outputs: Pass/Fail/Under Test Characteristics: Dry Contact relay Ele. Characteristics: 120V 100mA max.

Logic: Closed if True

Connector: 9 pin Male D-Series

Connector

Test Setups: 40 Memory Locations with 2 Steps each

80 Memory Locations with 1 Step each

Connectors: Front Connection (HV and Ground)

HV Socket

Ground (Binding Post)
Grnd Cont.(Banana Socket)

Front Panel Lockout: Key press with or without memory recall

Miscellaneous: Continuous Voltage on Fail

Zero Offset

Dimensions: $(w \times h \times d):11x4x14in$

(270x100x350mm)

Weight: 21 lbs (10kg) Shipping: 28 lbs (13kg)

Environmental: Meets MIL-T-28800E, Type 3, Class 5

Operating: 0° to + 40° C

Humidity: <75%

Storage: - 10° to + 60° C Warm-up Time: 1minute

Power: •90 - 130V AC •50 or 60Hz

•200 - 250V AC •300W max

Ordering Information

Sentry 10 AC Hipot Tester	700100 Ground Continuity Lead Calibration Certificate Traceable to NIST	S08	Gun Probe
Sentry 20 AC/DC Hipot Tester		S09	HV Lead, 1 meter, unterminated
Sentry 30 AC/DC/IR Hipot Tester	Optional Accessories: Calibration Data S02 HV Lead Set, 1m, (std w/unit) S03 Corded Product Adapter(115V) S04 HV Lead Set, 2m S05 Foot Switch S06 High Voltage Probe S07 Power Entry Adapter Cable	\$10	HV Lead, 2 meters, unterminated
Sentry 15 AC Hipot Tester		\$11	Gun Probe with remote start
Sentry 25 AC/DC Hipot Tester		\$12	Load Box, resistive
Sentry 35 AC/DC/IR Hipot Tester		\$14	Load Box, custom resistors
Includes:		\$15	Interconnection Cable to S50
Instruction Manual		\$16	Rack Mount Kit
700070 Power Cable		G16	International Power Strip
S02 Test Leads		G25	Corded Product Adapter (240V)

For more detailed specifications, visit www.quadtech.com
For more information about special purchase, rent & lease options, call
1-800-253-1230 • Fax 1-978-461-4295 • Intl. 1-978-461-2100

