# **AMPROBE®**



**Data Sheet** 

# AC75B Digital Clamp Meter with Temperature

Three tools in one: clamp meter, multimeter and thermometer

- 600 A AC current
- Digital thermometer 400 °C (1000 °F), Type K probe included
- AC/DC 750 V/1000 V
- 40 MΩ resistance
- Low DC µAmps for flame rod detector testing
- Capacitance to 4000 µF for motor run/start testing
- **■** Continuity beeper
- 4000-count large digit display
- Jaw size 35 mm (1.3")
- Auto power off
- **■** Low battery indicator
- Full overload protection
- One-year warranty

No hassle warranty

No waiting.

No shipping charges.



(note: \$500 MSLP limit)

Custom designed to make HVAC/R Service, Electrical, and Industrial maintenance tasks faster and easier. The AC75B combines a heavy-duty high-capacity 600A clamp-on meter with the most needed DMM functions such as resistance, continuity, and voltage measurement for general electrical troubleshooting. The AC75B then goes further than typical clamp meters and adds extra functions like a Type K digital thermometer, a high capacitance range, and display backlight. The extra features of the AC75B enable more specialized troubleshooting such as measuring flame rod safeguard current and testing motor run/start capacitors.

User safety is a prime concern of Wavetek Amprobe. The AC75B is fully safety engineered to US and Canadian standards and rated CAT III 600V. Test leads rated CAT II 1000V are included with the unit.













## **AC75B Digital Clamp Meter with Temperature**

**Data Sheet** 

# **General Specifications**

Operating temperature	0 °C - 50 °C	
Maximum jaw opening	Up to 1.3" (35 mm)	
Safety	Designed to meet IEC 1010-1 and IEC 61010-2-032, Class 2 and pollution degree 2 indoor use. Complies with CE and CSA 22.2 No. 1010-1 and No. 1010.2.032 requirements.	
Battery life	400 hours (alkaline)	
Power requirement	Standard 9 V battery NEDA 1604, JIS 006P	
Dimensions	84 mm (W) x 212 mm (L) x 40 mm (D) (3.3 x 8.4 x 1.6 inches)	
Weight	Approx. 390 g (15 oz.)	



## **AC75B Digital Clamp Meter with Temperature**

**Data Sheet** 

# Electrical Specifications (All at 23 $^{\circ}$ C $\pm$ 5 $^{\circ}$ C, <80 % R.H.)

Range	Accuracy
0 to 100 A	± (1.9 % + 2 A)
100 to 400 A	± (1.9 % + 1 A)
400 to 600 A	± (2.5 % + 7 A)
0.1A in 400 A range	
400, 4000 μA	±(1.0 %+2 d)
0.1 μΑ	
4, 40, 400, 750 V	±(1.5 %+5 d)
1 mV in 4 V range	
4, 40, 400, 1000 V	±(0.9 %+2 d)
1 mV in 4 V range	
MΩ	
400Ω	±(1.0 % + 2 d)
4 kΩ to 400 kΩ	±(0.7 % + 2 d)
4 M	±(1.0 % + 2 d)
40 MΩ	±(1.5 % + 2 d)
0.1 $\Omega$ in 400 $\Omega$ range	
1.5 mA	±(1.5 % + 5 d)
3 V	
approx. 200 $\Omega$	
2 kHz tone buzzer	
4 n, 40 n, 400 n, 4 μ, 40 μ, 400 μ, 4 mF	
4 n	$\pm (3.0 \% + 20 d)$
All other ranges	±(2.0 % + 8 d)
1 pF in 4 mF range	
-40 °C to .1 °C	±(1 % + 4 °C)
0 °C to 400 °C	±(1 % + 3 °C)
-40 °F to 32 °F	±(1 % + 8 °F)
32 °F to 750 °F	±(1 % + 6 °F)
750 °F to 1000 °F	±(2 % + 8 °F)
	0 to 100 A 100 to 400 A 400 to 600 A 0.1A in 400 A range  400, 4000 μA 0.1 μA 4, 40, 400, 750 V 1 mV in 4 V range  4, 40, 400, 1000 V 1 mV in 4 V range  MΩ 400Ω 4 kΩ to 400 kΩ 4 M 40 MΩ 0.1 Ω in 400 Ω range  1.5 mA 3 V  approx. 200 Ω 2 kHz tone buzzer  4 n, 40 n, 400 n, 4 μ, 40 μ, 400 μ, 4 mF 4 n All other ranges 1 pF in 4 mF range  10 °F) -40 °C to .1 °C 0 °C to 400 °C -40 °F to 32 °F 32 °F to 750 °F



#### **AC75B Digital Clamp Meter with Temperature**

**Data Sheet** 

#### **Included Accessories**

One pair test leads, Temperature Adapters (TA-1), Type K temperature probe (TP255A), 9 V battery (installed), operating instructions and carrying case with belt loop.

#### **Amprobe® Test Tools**

website: www.Amprobe.com email: info@amprobe.com

Everett, WA 98203 Tel: 877-AMPROBE

#### **Amprobe® Test Tools Europe**

In den Engematten 14 79286 Glottertal, Germany Tel.: +49 (0) 7684 8009 - 0

©2007 Amprobe Test Tools. All rights reserved. 9/2007 2123475 D-US-N Rev D