

# Fluke 287 FlukeView® Forms Combo Kit



Maximize productivity with the combined Fluke 287 and FlukeView forms combo kit. Designed for today's professionals involved in the R & D, maintenance, manufacture and design of electronic circuits or systems. With built-in data logger and TrendCapture (the meters on screen graphical display) cabability, the 287 helps you track down elusive, intermittent problems or monitor equipment with any of its functions. FlukeView Forms enables you to document, store, and analyze individual readings or series of measurements, overlay logged data to find cause and effect relationships, or turn your data into meaningful graphs and tables for a professional report. The 287/FVF combo kit gives you a practical and affordable approach to documenting circuit design performance.

### Fluke-287/FVF Kit includes:

- Fluke-287 True-rms Electronic Logging Multimeter with TrendCapture
- FlukeView Forms Software and cable
- 80BK-A Thermocouple Probe
- CAT III 1000 V 10 A Modular test leads (red, black)
- CAT III 1000 V 10 A Modular test probes (red, black)
- CAT II 300 V 5 A Alligator Clips (red, black)
- C280 Soft Case for meter protection and accessory storage

### **Technical Data**

### 287 functions and features

261 lunctions and	- ICULUI CD	
Multiple on-screen displays	Yes	
True-rms ac band- width	100 kHz	
DBV/dBm	Yes	
DC mV resolution	1 μV	
Megohm range	500 MΩ	
Conductance	50.00 nS	
Continuity beeper	Yes	
Temperature (°C and °F)	-200 °C to 1350 °C	
Battery/fuse access	Yes/Yes	
Elapse time clock	Yes	
Time of day clock	Yes	
Min-Max-Avg	Yes	
Frequency	Yes	
Duty cycle/pulse width	Yes	
Info button on board help	Yes	
Hold	Yes	
Isolated optical interface	Yes	
Auto/touch hold	Yes	
Reading memory	Yes	
Log to PC	Yes	
On board logging with TrendCapture	Yes	
Logging memory	180 hours	





## 287 specifications

Function	Range and resolution	Basic accuracy
DC volts	50.000 mV,500.00 mV, 5.0000 V, 50.000 V, 500.00 V, 1000.0V	0.025 %
AC volts		0.4 % (true-rms)
DC current	500.00 μA, 5000.0 μA, 50.000 mA, 400.00 mA, 5.0000 A, 10.000 A	0.06 %
AC current		0.6%(true-rms)
Temperature (excluding probe)	-200.0 °C to 1350.0 °C (-328.0 °F to 2462.0 °F)	1.0 %
Resistance	500.00 $\Omega$ , 5.0000 kΩ, 50.000 kΩ, 500.00 kΩ, 5.0000 MΩ, 50.00 MΩ,	0.05 %
Capacitance	1.000 nF,10.00 nF 100.0 nF, 1.000 μF, 10.00 μF, 100.0 μF, 1000 μF, 10.00 mF, 100.00 mF	1.0 %
Frequency	99.999 Hz, 999.99 Hz, 9.9999 kHz, 99.999 kHz, 999.99 kHz	0.005 % + 5

# Ordering information

Fluke-287/FVF True-rms Logging Multimeter Combo Kit with TrendCapture

### Fluke. Keeping your world up and running.®

### Fluke Corporation

PO Box 9090, Everett, WA 98206 U.S.A.

### Fluke Europe B.V.

PO Box 1186, 5602 BD Eindhoven, The Netherlands

#### For more information call: In the U.S.A. (800) 443-5853 or

Fax (425) 446-5116 In Europe/M-East/Africa +31 (0) 40 2675 200 or Fax +31 (0) 40 2675 222 In Canada (800)-36-FLUKE or Fax (905) 890-6866 From other countries +1 (425) 446-5500 or

Fax +1 (425) 446-5116 Web access: http://www.fluke.com

©2009 Fluke Corporation.

Specifications subject to change without notice. Printed in U.S.A. 3/2009 3451757 D-EN-N Rev A

Modification of this document is not permitted without written permission from Fluke Corporation.