

**TECHNICAL DATA** 

# Fluke T6 Electrical Testers with FieldSense technology





### Measure voltage...without test leads

Measure voltage up to 1000 V ac through the open fork, without test lead contact to live voltage.\* Without opening covers or removing wire nuts. On wires up to AWG 4/0 (120 mm<sup>2</sup>), carrying as much as 200 A. It will change your job. Safer. Faster. Easier.

### **Product Highlights**

- FieldSense technology for ac voltage, current and frequency measurement without making electrical contact to live voltage
- Simultaneous voltage and current display (T6-1000) shows all power supply measurements at a glance for efficient troubleshooting
- 1 to 1000 V ac or dc (T6-1000); 600 V ac or dc (T6-600)
- 0.1 to 200 A ac
- Resistance 1  $\Omega$  to 100 k $\Omega$  (T6-1000), 1  $\Omega$  to 1000  $\Omega$  (T6-600)
- Frequency measurement 45 Hz to 66 Hz (T6-1000)
- Works with wires up to AWG 4/0 (120 mm²) with a 17.8 mm jaw opening.
- HOLD button temporarily freezes the reading for easy viewing
- · Easy to read display with backlight
- · Accepts optional Fluke TPAK Magnetic Meter Hanger for convenient operation
- Standard two-year warranty; extendable to four years through product registration within 45 days of purchase\*
  - + Requires capacitive path to ground, provided through user in most applications. Ground connection via test lead may be required in some situations.
  - Register product online within 45 days of purchase to extend warranty to four years. See http://a.fluke.com/registration for details.















## **Specifications**

Measurement Specifications					
		T6-600	T6-1000		
Function	Requires test leads	Range	Range	Resolution	Accuracy <sup>[1]</sup>
FieldSense ac voltage	No	600 V	1000 V	1 V	±(3 % + 3 counts) <sup>[2] [3]</sup> 45 Hz - 66 Hz
FieldSense ac current	No	200.0 A	200.0 A	0.1 A	±(3 % + 3 counts) 45 Hz - 66 Hz
FieldSense frequency (Hz)	No		45 Hz – 66 Hz	1 Hz	±(1 % + 2 counts) [3]
Volts ac	Yes	600 V	1000 V	1 V	±(1.5 % + 2 counts) 45 Hz - 66 Hz
Volts dc	Yes	600 V	1000 V	1 V	±(1 % + 2 counts)
Resistance	Yes	1000 Ω	1000 Ω	1 Ω	±(1 % + 2 counts)
	Yes		10.00 kΩ	0.01 kΩ	
	Yes		100.0 kΩ	0.1 kΩ	
Safety (measurement category)		600 V CAT III	1000 V CAT III 600 V CAT IV		

Accuracy (1): ± ([% of reading] + [number of least significant digits]]. Accuracy is specified for 1 year after calibration, at 18 °C to 28 °C (64 °F to 82 °F) with relative humidity to 90 %. AC conversions are ac-coupled, RMS responding.

Accuracy <sup>(2)</sup>: Add 3 % without an external ground connection. External ground connection required for user wearing insulated gloves, standing on an insulated ladder and otherwise insulated from earth ground.

Accuracy (3): FieldSense specified from 16V to 100% of range.

#### **General Specifications** Calibration 1-year calibration cycle Dimensions 61.1 mm x 259.3 mm x 43.8 mm Fork opening 17.8 mm Temperature -10 °C to +50 °C (14 °F to 122 °F) -30 °C to +60 °C (-22 °F to +140 °F) Operating: Storage Altitude Operating: Storage: 2,000 m (6,562 feet) 10,000 m (32,808 feet) 0 % to 90 %, 5 °C to 30 °C (41 °P to 86 °P) 0 % to 75 %, 30 °C to 40 °C (86 °F to 104 °F) 0 % to 45 %, 40 °C to 50 °C (104 °F to 122 °F) Relative Humidity Battery Type and Life 2 x AA (IEC LR6); 360 hours continuous, typical; 200 hours using RF Field Specification 0.5 % full scale + (specified accuracy) at 3 V / m **Enclosure Rating** IP 52 per IEC/EN 60529, no vacuum applied Temperature coefficient 0.1 x (specified accuracy) / °C for <18°C or >28 °C (< 64.4 °F or > 82.4 °F) IEC/EN 61010-1, IEC/EN 61010-2-033: Pollution Degree 2 Electromagnetic Environment IEC/EN 61326-1: Portable

## Fluke. Keeping your world up and running.®

#### Fluke Corporation

PO Box 9090, Everett, WA 98206 U.S.A.

#### Fluke Europe B.V.

PO Box 1186, 5602 BD Eindhoven, The Netherlands

Modification of this document is not permitted without written permission from Fluke Corporation.

#### For more information call:

In the U.S.A. (800) 443-5853 or Fax (425) 446-5116 In Europe/M-East/Africa +31 (0)40 267 5100 or Fax +31 (0)40 267 5222 In Canada (800)-36-FLUKE or Fax (905) 890-6866 From other countries +1 (425) 446-5500 or Fax +1 (425) 446-5116 Web access: http://www.fluke.com

©2017 Fluke Corporation. Specifications subject to change without notice. 7/2017 6009251a-en

### **Ordering information**

Fluke T6-600 Electrical Tester

Fluke T6-1000 Electrical Tester

#### **Included with product**

Attached test leads with removable 4 mm probe caps, user documentation

### **Optional accessories**

H-T6 Belt Holster

**TPAK Magnetic Hanger** 

**PRV240FS Proving Unit** 

TP1 Probe Set, Flat-Blade (US/UK flat tip)

TP38 Probe set, round (EU)

**AC285 SureGrip Alligator Clips** 

**AC220 SureGrip Alligator Clips** 

Service Information Sheet, PN 686953

<sup>\*</sup> Two-year additional warranty offer may be discontinued without notice