

## American Hakko Products, Inc.



**Bulletin No:** PB294

Issue Date: 2-3-2010

Available: February 2010

## **Product Description:**

373 Solder Feeder Assembly for the Hakko FM-2027 Connector

Part No:

Various – See Specifications below.



## Specification:

Solder Ø	Tube Unit	Guide Pipe Assy.
0.6/0.65mm		B3481
0.8mm	B3477	B3482
1.0mm		B3483
1.2mm	B3478	B3484
1.6mm		

NOTE: 1.6mm Ø is NOT available for use.

## Comments:

These new tube units for the 373 Solder Feeder are now compatible with the FM-2021 and FM-2027 Connectors. The larger 1.6mm diameter solder cannot be used due to the rigidity of the solder at that diameter.



Tube Unit (B3478 Pictured)



Guide Pipe Assembly (B3484 Pictured)

For more information on the Hakko 373 Solder Feeder and various assemblies to fit your Hakko soldering station, please visit our website at www.HakkoUSA.com.

For additional information:

- End-User Customers Call Customer Support at 1-800-88-HAKKO (42556) ٠
- Authorized Distributors Call Distributor Support at 661-294-0090

American Hakko Products. Inc. 28920 Avenue Williams. Valencia, CA 91355 Tel: (661) 294-0090 Fax: (661) 294-0096 www.HakkoUSA.com AHP14 Rev 2007-12

From...

28920 Avenue Williams • Valencia • California 91355

www.valuetronics.com