



American Hakko Products, Inc.

## P R O D U C T   B U L L E T I N

**Bulletin No:** PB217

**Issue Date:** May 23, 2005

**Product:**  
485 Soldering System

**Part No:**  
485-V12 and 485-1-V12

**Specification:**  
This is a specification change only. The 485 system will no longer include solder.

**Comments:**  
Due to the increased use of lead free and other solder compositions the 485 will now be available with an empty solder pot. Previously, customers would have to empty and clean the solder pot when using any solder other than the supplied Sn63 solder. Shipping the 485 without solder will save time and effort for the customer. All 485 stations shipped after the available date will have empty solder pots.

**Available:**  
May 23, 2005



From...

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

American Hakko Products, Inc.  
28920 N. Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
www.hakkousa.com  
AHP14 Rev 2000-01